



STATE OF FLORIDA
DEPARTMENT OF HEALTH
COUNTY HEALTH DEPARTMENT
FOOD SERVICE
INSPECTION REPORT



2 of 2

Violations Comments Section

38. Vermin control

Repair or replace the air curtain (fly-fan) above the southside backdoor close to the mop sink and the laundry area.

Vermin. 64E-11.007(7). Effective measures shall be taken to protect against rodents, flies, roaches and other vermin. All openings to the outside are protected against vector entrance.

39. Other facilities and operations

Repair a big hole in the wall of the laundry area close to the clothes dryer.

Other Facilities. 64E-11.008. Floors, walls, and ceilings shall be smooth and washable. 20 foot candles of light shall be provided. Adequate ventilation shall be provided. A mop sink or garbage can wash down will be provided. No living quarter shall open to the facility. No live animals. Exterior area shall be kept clean.

Inspection Conducted By: Osvaldo Samper (67699)
Phone: (305) 623-3500
Received By: Signed
Date: 6/1/2016

Inspector Signature:

Client Signature: